



Isf = 400A
Isn = 100A
Long I = 1x
Slop = Flat
Long T = 20s
Short I = 5 x
Short T = 5s
Inst = 11x
Ground I = 0,9 x
Ground T = 1s